UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF

THE DEPENDENT RESURVEY OF

A PORTION OF THE FIFTH STANDARD PARALLEL SOUTH (NORTH BOUNDARY),

A PORTION OF THE GUIDE MERIDIAN BETWEEN RANGES 6 AND 7 WEST

A PORTION OF THE SOUTH BOUNDARY,

A PORTION OF THE SUBDIVISIONAL LINES,

THE SUBDIVISION OF SECTIONS,

1, 12, 13, 14, 23, 24, 27, AND 35,

AND

THE DEPENDENT RESURVEY OF MINERAL SURVEYS,

LOT 57A, WASHINGTON LODE AND LOT 58 NEWARK LODE

ΙN

TOWNSHIP 26 SOUTH RANGE 7 WEST

OF THE SALT LAKE MERIDIAN IN THE STATE OF UTAH

EXECUTED BY

Larry V. Judd Cadastral Surveyor

Under Special Instructions dated March 24, 2005, approved March 24, 2005, which provided for the surveys included under Group Number 1001, and Assignment Instructions dated March 24, 2005 and Reassignment Instructions dated July 14, 2009.

Survey commenced April 28, 2005 Survey completed July 7, 2005

INDEX DIAGRAM

Township 26 South, Range 7 West

						-			
						6		5	5
6	5	4	3		2	26		1	12
_	_	_							
							25	24	11
						23			
7	8	9	10		11	22		12	10
, i	0	,				22			10
				34	35	22	21	21	9
						20			
10	4.5	7.0	45	34	14	20		13	9
18	17	16	15	24	14	20		13	,
				32	33	18		18	19
								0.4	7
19	20	21	22	31	23	17		24	7
		37	38	30	31	15		16	6
30	29	28 37	27	30	26	15		25	
		36	37	28	29	14			
		36	1 3/	20	23	<u></u>			······································
31	32	33	34	27	35	14		36	
				17	13	12			
				13	13	12	<u> </u>		-

The	Subdivision	of	Section	1Page	39
The	Subdivision	of	Section	12Page	41
The	Subdivision	of	Section	13Page	43
The	Subdivision	of	Section	14Page	44
The	Subdivision	of	Section	23Page	45
The	Subdivision	of	Section	24Page	47
The	Cubditioion	of.	Scation	27Page	48
The	Subdivision	01	Section	35Page	50
The	Subdivision	OI	Section	Page	53
Lot	57A Washingt	on	Lode	Page	55
Lot	58 Newark Lo	ode.			55

TOWNSHIP 26 SOUTH, RANGE 7 WEST, SALT LAKE MERIDIAN, UTAH.

The following field notes are those of the dependent resurvey of a portion of the Fifth Standard Parallel South (north boundary), a portion of the Guide Meridian between Ranges 6 and 7 West (east boundary), a portion of the south boundary, a portion of the subdivisional lines, the subdivision of sections 1, 12, 13, 14, 23, 24, 27, and 35, and the dependent resurvey of, Washington Lode, Lot 57A AM. and Newark Lode, Lot 58 AM., in T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

History of Surveys

	Surveyed by	Retr. or Resurveyed by						
SOUTH BOUNDARY								
Portion Portion All	J. Bausman Page & Erwin	1869 1901	C.P. Sylvester	1969				
EAST BOUNDARY (Guide Meridian)								
Portion All Portion	J. Bausman Page & Erwin	1869 1900	Page & Erwin C.P. Sylvester	1900 1969				
WEST BOUNDARY								
All Portion	Page & Erwin	1901	L.V. Judd	1996				
NORTH BOUNDARY (Fifth Standard Parallel South)								
All All Portion	J. Bausman	1869	Page & Erwin Miller & Byergo	1901 1919				
SUBDIVISION	ī							
Portion Portion Portion Portion	J. Bausman F. Dickert J. Bausman Page & Erwin	1869 1870 1870 1901	J. Bausman Page & Erwin L.V. Judd	1870 1901 1996				
MINERAL SURVEYS								
Lot 57A Washington Lode and Lot 58 Newark Lode								
All All	E. Koeber	1886	O. Palmer	1891				

HISTORY OF LOCAL SURVEYS

In 1987, Bush & Gudgell, Inc. of St. George, Utah preformed a survey for June Fletcher in section 23. The record of survey was obtained directly from Bush and Gudgell, Inc.

TOWNSHIP 26 SOUTH, RANGE 7 WEST, SALT LAKE MERIDIAN, UTAH.

In 2001, Watson Engineering Company, Inc. of Cedar City, Utah preformed a survey of the Sulphurdale interchange, in sections 14 and 23. This survey was recorded on October 25, 2001, in the Beaver County Engineers Office as Plat number 251.

In 2003, Grimshaw Surveying, Inc. of Enoch, Utah preformed an ALTA/ACSM Land Title Survey in section 12 and a portion of section 14. This survey consists of 4 sheets and was recorded on July 7, 2003, in the Beaver County Engineers Office as Plat number 285a, 285b, 285c, and 285d.

The Beaver County Surveyors office has monumented several corners within the project area, with Corner Perpetuation and Filing Records on file in the Beaver County Recorders Office.

T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

This survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions for Group No. 1001, dated March 24, 2005.

The direction of the lines was determined by references to true meridians, established by Global Positioning System (GPS) utilizing Real-Time Kinematic (RTK) techniques throughout the survey. The positional accuracy of this survey complies with the Standards and Guidelines for Cadastral Surveys Using GPS Methods, dated May 9, 2001, Version 1.0. Trimble model 5700 GPS receivers were used for field collection. Cadastral Measurement Management (CMM) software was the primary software utilized for project calculations.

Preliminary to the resurvey, the lines of the prior surveys were retraced and search was made for all corners and their calls of record. Identified corners were remonumented in their original positions. Lost corners were reestablished and remonumented at proportionate positions based on the official record. The retracement data was thoroughly verified and only the true line field notes are given herein.

Geodetic control was derived from National Geodetic Survey Station "PINEY" with the published data as follows:

Latitude: 38°30'12.58015" N. Longitude: 112°39'18.93928" W. N.A.D. 1983 (1994) Elevation 7313 feet, N.A.V.D., 1988.

The geographic position of the standard corner of sections 35 and 36 only, determined by using RTK methods from indirect ties made to National Geodetic Survey Station "PINEY" is as follows:

Latitude: 38°29'54.526" N. Longitude: 112°36'02.607" W. N.A.D. 1983.

T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Previous surveys of the Fifth Standard Parallel South, reference the standard corner of section 35 and 36 as common to all four sections, while another survey established a closing corner for sections 1 and 2.

The following paragraphs briefly describe the history of the surveys along a portion of the Fifth Standard Parallel South, between sections 1 and 36. For a complete record see the official field note and plat returns.

The original survey of the Fifth Standard Parallel South was executed by J. Bausman in 1869; he set a black lava stone, 18x8x7 inches for the corner of section 35 and 36.

In 1870, F. Dickert, while surveying section 1, in Township 26 South, Range 7 West, intersected the Fifth Standard Parallel South 18 links west of the standard corner of section 35 and 36, where he set a lava stone, 15x12x5 inches for the closing corner of sections 1 and 2.

The north boundary of the township was resurveyed by Page and Erwin in 1901, at which time they found lying loose, a lava stone 18x9x8, (the apparent Bausman stone) and reset it as the standard corner of sections 35 and 36. While resurveying the subdivisional lines of the township, they ran north between sections 1 and 2 and intersected the Fifth Standard Parallel South at the standard corner of sections 35 and 36. Having not found the 1/4 section corner of sections 1 and 2, they proportioned it between the southwest corner of section 1 and the standard corner of sections 35 and 36, making the standard corner common to all four sections. They made no mention of the closing corner set by Dickert in 1870.

In 1919, Miller and Byergo resurveyed the Fifth Standard Parallel South, they found a lava stone, 8x8x8 inches above ground, and remonumented the corner with a 2 inch diameter iron post marked common to all four sections, 1, 2, 35 and 36.

At the present time, the iron post as described by Miller and Byergo remains as well as a lava stone, 21x9x8 inches, marked 1 groove on east, 5 grooves on west, and SC on north faces, set alongside the iron post. The corner is located in a north south fence line. No remaining evidence of the closing corner set by Dickert in 1870 was found.

The standard corner of sections 35 and 36 is accepted as currently monumented, common to all four sections. All patented lands in the area were patented after the 1900-1901 survey which discarded the closing corner of sections 1 and 2, and made the standard corner common to all four sections.

DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY (FIFTH STANDARD PARALLEL SOUTH), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Dependent Resurvey of a Portion of the North Boundary (Fifth Standard Parallel South) T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by J. Bausman in 1869 and the Resurvey Executed by Page and Erwin in 1901

Beginning at the corner of Townships 25 and 26 South, Ranges 6 and 7 West, monumented with an iron post, 2 1/2 inches diameter, firmly set in a small mound of stone, with the brass cap marked as described in the official record of the 1982 resurvey.

Corner is located in a fence line extending north and south on the east edge of an open rolling pasture.

S. 89° 54.3′ W., on the Fifth Standard Parallel South, between sections 1 and 36.

40.061 The standard 1/4 section corner of sections 1 and 36, monumented with a Millard County Survey Monument, an aluminum pipe, 3 inches diameter, firmly set, projecting 16 inches above ground, with the aluminum cap marked:

Found a steel fence post alongside.

Corner is located 69 feet east, of a fence line extending north and south.

This corner is accepted as a careful and faithful determination of the position of the 1/4 section corner by proportionate methods. No remaining evidence of the original marked stone was found.

s. 89° 54.4′ W., beginning new measurement.

20.031 Point for the W 1/16 section corner of sections 1 and 36.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY (FIFTH STANDARD PARALLEL SOUTH), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Set a fiberglass fence post alongside.

Corner is located at base of lava rim, 20 feet high, bearing north and south.

From which, a rebar, 5/8 inch diameter, without attached identifying cap, firmly set, projecting 2 inches above ground, bears south, 3.4 feet distance.

40.062 The standard corner of sections 1, 2, 35, and 36, monumented with an iron post, 2 inches diameter, firmly set, projecting 12 inches above ground, with the brass cap marked as described in the official record of the 1919 resurvey.

Alongside the iron post, found a lava stone, 21x9x8 inches, plainly marked with 1 groove on the east, 5 grooves on the west, and a SC on the north faces.

Corner is located in a fence line extending north and south.

Found a mound of stone 4x3x2 feet west of the iron post.

Dependent Resurvey of a Portion of the West Boundary (Guide Meridian), T. 26 S., R. 6 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by Page and Erwin in 1900

From the corner of sections 19 and 30 only, T. 26 S., R 6 W., monumented with a trachyte stone 18x8x4 inches, lying loose, plainly marked with 2 grooves on one edge and no other marks found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 14 inches in the ground to solid rock, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 3 foot base, to the aluminum cap marked:

Corner is located on steep north slope in piñon and oak brush.

CHAINS

From this corner, the closing corner of sections 24 and 25, monumented with a trachyte stone 16x12x3 inches, loosely set, dimly marked CC on the west face, and plainly marked with 2 notches on the south, and 4 notches on the north edges, bears S. 2° 44.3′ W., 7.257 chains distance.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26S R7W R6W S24 C S25 C 2005

Bury the marked stone along side the aluminum post.

Raise a mound of stone 2x2x1 feet west of the aluminum post.

Corner is located on steep south slope in piñon and juniper.

N. 0° 16.6' W., on the west boundary of section 19.

32.692 Point for the 1/4 section corner of section 24 only, T. 26 S., R. 7 W.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground to solid rock, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 4 foot base, to the aluminum cap marked:

T26S R7W R6W 1/4 S24

Corner is located on south slope in piñon and juniper.

Set a steel fence post alongside the aluminum post.

40.185 The 1/4 section corner of section 19 only, T. 26 S. R 6 W., monumented with a trachyte stone 16x10x8 inches, firmly set, plainly marked 1/4 S 19 on the west face.

From which

A piñon 18 inches diameter, scribed 1/4 S19 BT, on an open blaze bears, N. 67° E., 19 links distance. (Record N.16°E., 28 links distance.)

CHAINS

A juniper 8 inches diameter, scribed 1/4 S BT, on an open blaze bears, S. 86° W., 6 links distance. (Record a piñon, at N. 15° W., 32 links distance.)

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26S R7W R6W | 1/4 | S19 2005

Bury the marked stone alongside the aluminum post.

Corner is located on southwest slope in piñon and juniper.

Raise a mound of stone 3x2x1 feet, east of the aluminum post.

N. 0° 25.1' E., beginning new measurement.

- 32.448 True point for the closing corner of sections 13 and 24, T. 26 S., R. 7 W., hereinafter described.
- 39.480 The corner of sections 18 and 19 only, T. 26 S. R 6 W., monumented with a trachyte stone 12x10x2 inches, plainly marked with 3 grooves on the north and south edges, set in a small scattered mound of stone.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Bury the marked stone alongside the aluminum post.

Corner is located on north slope in dense piñon, juniper, and oak brush.

Raise a mound of stone 4x3x2 feet, east of the aluminum post.

CHAINS

N. 0° 09.2' W., on the west boundary of section 18.

Point for the 1/4 section corner of section 13 only, T. 26 S., R. 7 W.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26S R7W R6W 1/4 S13 2005

Raise a mound of stone 3x2x1 feet west of the aluminum post.

Corner is located on a gradual southwest slope in an old chaining.

From this corner, the corner of fences, extending north and west bears, N. 79° W., 44.5 feet distance.

40.193 Point for the 1/4 section corner of section 18 only, T. 26 S. R 6 W., at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 18 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 5 foot base to the aluminum cap marked:

T26S R7W R6W 1/4 S18 2005

Corner is located on steep northwest slope in piñon and juniper, 32 feet east of a fence line extending north and south.

73.222 The corner of sections 7, 12, 13, and 18, monumented with a U.S. Forest Service Survey monument, an aluminum post, 3 inches diameter, firmly set in a mound of stone, with the aluminum cap marked:

T26S R7W R6W S12|S 7 S13|S18 LS 4876

CHAINS

A red sandstone $24 \times 10 \times 4$ inches, plainly marked with 4 notches on one edge and 2 notches on the opposite was found buried alongside the aluminum post.

from which

- A juniper 12 inches diameter, with a healed over blaze bears, S. 48° E., 45 links distance. (Record 30 links)
- A juniper 12 inches diameter, with a healed over blaze bears, S. 55° W., 50 links distance.

The northeast and northwest bearing trees were found dead and down, not re-measured.

Corner is located in a fence line extending east and west, and at the projection of fences extending south and N. 30 $^{\circ}$ W.

Reestablishment of the Survey Executed by J. Bausman in 1869 and the Resurvey Executed by Page and Erwin in 1900

- N. 1° 04.5' E., between sections 7 and 12.
- 19.481 Intersect line 1-4, Washington Lode, Lot 57A, AM., not monumented.
- 24.679 Intersect line 3-4, Washington Lode, Lot 57A, AM., not monumented.
- 40.214 The 1/4 section corner of sections 7 and 12, monumented with a U.S. Forest Service Survey monument, an aluminum post, 3 inches diameter, firmly set in a small mound of stone, with the aluminum cap marked:

T26S R7W R6W 1/4 S12 | S 7 LS 4876 1986

from which

- A juniper 22 inches diameter, with an open blaze, and no visible scribing, bears N. 66° E., 64 links distance. (Record N. 63 1/4° E., 161 links distance).
- A juniper 30 inches diameter, with an open blaze, and no visible scribing, bears S. 78° W., 120 links distance.

Corner is located in a fence line extending north and south, 3 feet north of a fence corner extending north and west, and 20

CHAINS

feet north of center line of dirt road, 10 feet wide bearing east and south.

N. 0° 48.9' E., beginning new measurement.

40.159 The corner of sections 1, 6, 7, and 12, monumented with a U.S. Forest Service Survey monument, an aluminum post, 3 inches diameter, firmly set in a mound of stone, with the aluminum cap marked:

T26S R7W R6W S 1 S 6 S12 S 7 LS 4876 1986

from which

- A juniper stump 16 inches diameter, with no visible scribe marks bears, S. 40° E., 40 links distance.
- A juniper stump 12 inches diameter, with no visible scribe marks bears, S. 70° W., 161 links distance.
- A juniper 22 inches diameter, with a healed over blaze, bears, N. 67° W., 143 links distance. (Record N. 72 1/2° W., 138 links)

The corner falls at the corner of fences, extending north, south and west.

N. 0° 21.9' E., between sections 1 and 6.

The S 1/16 section corner of sections 1 and 6, monumented with a rebar, 5/8 inch diameter, without attached identifying cap, firmly set, projecting 4 inches above ground, with a steel fence post alongside.

The rebar is accepted as a careful and faithful determination of the 1/16 section corner position. No determination was made as to who or when the rebar was set.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at base and the rebar inside post, with the aluminum cap marked:

CHAINS

S 1/16 S 1 | S 6 2005

Raise a mound of stone 3x2x1 feet west of the aluminum post.

Corner is located on a west slope, 2 feet west of a fence line extending north and south, in an open juniper area.

40.088 The 1/4 section corner of sections 1 and 6, monumented with a fence corner with fences extending north, east, south, and west. The corner of fences is accepted as the best available evidence of the position of the original corner.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26S R7W R6W 1/4 S 1 | S 6 2005

N. 0° 43.7' E., beginning new measurement.

40.422 The corner of Townships 25 and 26 South, Ranges 6 and 7 West, hereinbefore described.

Dependent Resurvey of a Portion of the South Boundary, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by J. Bausman in 1869 and the Resurvey Executed by C.P. Sylvester in 1969

From the corner of sections 35 and 36 only, on the south boundary of the township, monumented with an iron post, 2 1/2 inches diameter, firmly set, with the brass cap marked as described in the official record of the 1969 resurvey.

Found the original granite stone, lying loose alongside the iron post 17x7x6 inches, plainly marked with 5 notches on one edge and 1 notch on the opposite.

Bury the marked stone alongside the iron post.

Corner is located on a south slope, at the corner of fences extending north, east, and west, on the east side of a

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

two-track road, bearing south and west in scattered piñon and juniper.

S. 88° 01.1′ W., on the south boundary of the township.

1.293 The closing corner of sections 1 and 2, T. 27 S., R. 7 W., monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 12 inches above ground, with the brass cap marked as described in the official record of the 1969 resurvey.

Raise a mound of stone around the iron post.

Corner falls 2 feet south of ${\tt E}$ - ${\tt W}$ barbed wire fence, and amongst scattered piñon in an old chained area.

40.192 The 1/4 section corner of section 35 only, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 6 inches above ground, with the brass cap marked as described in the official record of the 1969 resurvey.

No remaining evidence of the 1969 bearing tree was found.

Corner is located in flat open brush and in a fence line extending east and west; a two track road runs parallel to the fence, 10 feet north of the corner.

S. 88° 05.8' W., beginning new measurement.

1.134 The 1/4 section corner of section 2 only, T. 27 S. R. 7 W., monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 6 inches above ground, with the brass cap marked as described in the official record of the 1969 resurvey.

Found a small mound of stone to the south of the iron post.

No remaining evidence of the original bearing trees were found.

Corner is located in flat open country, 2 feet north of a fence line extending east and west; a two track road runs parallel to the fence, 10 ft. north of the corner.

S. 87° 57.5' W., beginning new measurement.

39.034 The corner of sections 34 and 35 only, monumented with an iron post, 2 1/2 inches diameter, firmly set, projecting 8 inches above ground, with the brass cap marked as described in the official record of the 1969 resurvey.

from which

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

A burned, dead juniper 14 inches diameter, with an open blaze, and no visible scribing, bears, N. 46° E., 55 links distance. (Record N. 48° 30' E., 35 links distance.)

The northwest bearing tree was found dead and down, not remeasured.

Found a mound of stone 3x2x2 north of the corner, with steel fence post along side.

Corner is located on open flat ground.

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey Executed by J. Bausman in 1870, and the Resurvey Executed by Page and Erwin in 1901

From the corner of sections 35 and 36 only, on the south boundary of the township, hereinbefore described.

N. 0° 01.6' E., between sections 35 and 36.

Point for the 1/4 section corner of sections 35 and 36 at proportionate distance. No remaining evidence of the original corner was found.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W 1/4 S35 | S36 2005

Corner is located 1.5 feet west of a fence line extending north and south in piñon and juniper.

Raise a mound of stone 4x3x2 feet, west of the aluminum post.

- 57.690 Point for the N 1/16 section corner of sections 35 and 36, not monumented.
- 76.920 The corner of sections 25, 26, 35, and 36, monumented with a granite stone 20x12x9 inches, firmly set, plainly marked with 1 notch on the south and east edges, set in a mound of stone.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, with magnet enclosed in a clear

CHAINS

plastic case at the base, in a mound of stone 3 foot base, to the aluminum cap marked:

> T26SR7W <u>S26 | S25</u> <u>S35 | S36</u> 2005

from which bearing trees not of record

- A juniper 18 inches diameter, with a nail set in an open blaze, bears, S. 27° E., 13 links distance.
- A juniper 12 inches diameter, with a nail set in an open blaze, bears, N. 60° W., 26 links distance.

Bury the marked stone alongside the aluminum post.

Corner is located 3 feet east of a fence line extending north and south in piñon and juniper.

N. 0° 12.6' E., between sections 25 and 26.

40.528 The 1/4 section corner of sections 25 and 26, monumented with a granite stone, 16x14x7 inches, firmly set in a mound of stone, plainly marked 1/4 on the west face.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W 1/4 S26 | S25 2005

Bury the marked stone alongside the aluminum post.

Corner is located in a fence line extending north and south in flat open brush.

N. 0° 12.5' E., beginning new measurement

40.535 The corner of sections 23, 24, 25, and 26, monumented with a granite stone, 24x12x10 inches, firmly set, plainly marked with 2 notches on the south and 1 notch on the east edges.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

CHAINS

T26SR7W S23 | S24 S26 | S25 2005

from which

A juniper 16 inches diameter, with scribing visible through a mostly healed over blaze, bears west, 347 links distance.

The northeast bearing tree was found dead and down, not re-measured.

Bury the marked stone alongside the aluminum post.

Corner is located at the corner of fences extending north, east, south, and west.

Reestablishment of the Survey Executed by Page and Erwin in 1901

S. 89° 31.7′ E., between sections 24 and 25.

39.960 The 1/4 section corner of sections 24 and 25 monumented with a fence corner with fences extending north and west. The corner of fences is accepted as the best available evidence of the position of the original corner.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Corner is located on a southwest slope in dense oak brush.

Raise a mound of stone 3x2x1 feet, north of the aluminum post.

S. 88° 44.2' E., beginning new measurement.

41.592 The closing corner of sections 24 and 25 on the east boundary of the township, hereinbefore described.

Reestablishment of the Survey Executed by J. Bausman in 1870, and the Resurvey Executed by Page and Erwin in 1901

CHAINS

From the corner of sections 23, 24, 25, and 26.

N. 0° 13.1' E., between sections 23 and 24.

40.473 The 1/4 section corner of sections 23 and 24, monumented with a steel fence post, set in a mound of stone. The steel fence post has been utilized by others as the 1/4 section corner point, and is accepted during the execution of this survey as the best available evidence of the position of the original corner. No definitive evidence of the original marked stone was found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W 1/4 S23 | S24 2005

Corner is located on southwest slope in dense oak brush.

Raise a mound of stone 4x2x1 feet west of the aluminum post.

Reset the steel fence post alongside the aluminum post.

Corner is located N. 30° E., 7 feet from the corner of fences extending south and west, and 15 feet west of a two-track dirt road bearing north and south.

N. 0° 24.4' E., beginning new measurement.

19.226 Point for the N 1/16 section corner of sections 23 and 24.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 20 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone 3 foot base, to the aluminum cap marked:

N 1/16 S23 | S24 2005

Set a steel fence post alongside the aluminum post.

Corner is located 36 feet north of a fence line extending east and west, in an open juniper area.

From this corner, a rebar with attached cap marked REW 145764 bears S. 11° 43′ W., 17.6 ft. distance, not utilized.

CHAINS

38.452

The corner of sections 13, 14, 23, and 24, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, projecting 10 inches above ground, in a small mound of stone, with an attached 3 1/4 inch diameter aluminum cap marked:

T26SR7W
S14|S13
S23|S24
LS 174457
2003

Found a steel fence post alongside the aluminum post.

The position of the section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located in flat pasture.

Reestablishment of the Survey executed by Page and Erwin in 1901

S. 89° 46.1' E., between sections 13 and 24.

20.759 Point for the W 1/16 section corner of sections 13 and 24.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located 2 feet east of a fence line extending north and south in sagebrush flat.

41.518 The 1/4 section corner of sections 13 and 24 monumented with a trachyte stone 18x15x5 inches, lying loose, plainly marked 1/4 S13 on one side.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 3 foot base to the aluminum cap marked:

CHAINS

Bury the marked stone alongside the aluminum post.

Set a steel fence post alongside the aluminum post.

Corner is located 3 feet west of a fence line extending north and south on a southwest slope in piñon and juniper, and 30 feet north of a wash draining west.

S. 89° 49.3' E., beginning new measurement.

39.768 The closing corner of sections 13 and 24, monumented with a trachyte stone 24x12x3 inches, firmly set, plainly marked CC on the west face, 3 notches on the south edge, and 3 notches on the north edge. Add the marks AM on the west side of stone and bury in place.

from which, a bearing tree not of record,

- A juniper 10 inches diameter, with scribe marks, S 13 B visible on a mostly healed over blaze, bears, N. 71° W., 32 links distance.
- 39.968 The true point for the closing corner of sections 13 and 24, at intersection with the Guide Meridian between Ranges 6 and 7 West, hereinbefore described.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 12 inches in the ground, to solid rock, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 4 feet base with the aluminum cap marked:

From which, the bearing tree described above bears, N. 78° W., 51 links distance.

Corner is located on gradual southwest rocky slope in dense piñon and juniper.

Reestablishment of the Survey Executed by J. Bausman in 1870, and the Resurvey Executed by Page and Erwin in 1901

CHAINS

 $N.~0\,^{\circ}~10.8'~W.\,,$ on the west boundary of section 13.

The 1/4 section corner of sections 13 and 14, monumented with a rebar, 5/8 inch diameter, with attached 2 inch diameter aluminum cap marked GRIMSHAW SURVEYING 1/4 S13 S14 2003 LS174457. The rebar with cap are accepted as a careful and faithful determination of the 1/4 section corner position by proportionate measurement. No remaining evidence of the original corner was found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 6 inches below the surface of the ground, with magnet enclosed in a clear plastic case at the base with the rebar and cap inside post, with the aluminum cap marked:

T26SR7W 1/4 S14 | S13 2005

Corner is located on the east edge of a gravel road, 25 feet wide, bearing N. 13 $^{\circ}$ E., and S 13 $^{\circ}$ W.

N. 0° 10.8′ W., beginning new measurement.

38.068 The closing corner of sections 12 and 14 only, monumented with a rebar, 5/8 inch diameter, firmly set, projecting 2 inches above ground, with an attached 2 inch diameter aluminum cap marked GRIMSHAW SURVEYING S12 S13 S14 2003 LS174457, and a steel fence post set alongside.

Lying loose alongside the rebar, found a sandstone 12x8x4 inches plainly marked CC on one face, 4 notches on one edge and 1 notch on another.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base with rebar and cap inside post, with the aluminum cap marked:

T26SR7W <u>S12 C|</u> S14 C| 2005

Bury the marked stone alongside the aluminum post.

Corner is located in a fence line extending east and west in sagebrush flat.

CHAINS

40.507

The northwest corner of section 13 only, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, with an attached 3 1/4 inch diameter aluminum cap marked:

LS 174457 T26SR7W S13

Found a steel fence post alongside the aluminum post.

The position of the section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located in sagebrush flat.

Reestablishment of the Survey Executed by J. Bausman in 1869 and the Resurvey Executed by Page and Erwin in 1901

From the corner of sections 7, 12, 13, and 18, on the Guide Meridian, between Ranges 6 and 7 West, hereinbefore described.

N. 88° 13.1' W., between sections 12 and 13.

40.143 The 1/4 section corner of sections 12 and 13 monumented, with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, projecting 4 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

LS 174457 T26SR7W S 12 1/4 S 13 2003

Found a steel fence post alongside the galvanized post and a mound of stone 3x2x1 feet north of the galvanized post.

The position of the 1/4 section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located in piñon and juniper flat.

CHAINS

 $N.~87^{\circ}~29.0^{\circ}~W.$, beginning new measurement.

20.751 The W 1/16 section corner of sections 12 and 13, monumented with a rebar, 5/8 inch diameter, firmly set, with an attached 2 inch diameter aluminum cap marked GRIMSHAW SURVEYING W 1/16 LS174457.

The rebar with cap are accepted as a careful and faithful determination of the 1/16 section corner position.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base with the rebar and cap inside post, with the aluminum cap marked:

Found a steel fence post alongside the aluminum post.

Corner is located in an old chaining on flat ground in sage and young piñon and juniper growth.

41.502 The northwest corner of section 13 only.

Reestablishment of the Survey executed by Page and Erwin in 1901

From the south corner of section 11 and 12 only, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, projecting 2 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

LS 174457 T26S R7W S11 | S12 S14 2003

Found a steel fence post alongside the galvanized post.

The position of the section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

CHAINS

Corner is located in fence line extending east and west in a sagebrush flat.

 $N.~0^{\circ}~01.4'~E.$, between sections 11 and 12.

40.087 The 1/4 section corner of sections 11 and 12, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, projecting 4 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

LS 174457 T26SR7W S11 | S12 1/4 2003

Found a steel fence post alongside the galvanized post.

The position of the 1/4 section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located in sagebrush flat.

N. 0° 01.1' W., beginning new measurement.

20.020 Point for the N 1/16 section corner of sections 11 and 12, monumented with a rebar, 5/8 inch diameter, with an attached 2 inch diameter aluminum cap marked GRIMSHAW SURVEYING N 1/16 LS174457.

The rebar with cap are accepted as a careful and faithful determination of the 1/16 section corner position.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar and cap inside post, with the aluminum cap marked:

Found a steel fence post alongside the aluminum post.

Corner is located on flat ground in sagebrush.

40.040 The north corner of sections 11 and 12 only, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches

CHAINS

diameter, firmly set, projecting 2 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

LS 174457
T26S R7W
S 2
S11 S12
2003

Found a steel fence post alongside the galvanized post and a small mound of stone west.

The position of the section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located in flat open brush.

Reestablishment of the Survey Executed by F. Dickert in 1870 and the Resurvey Executed by Page and Erwin in 1901

From the corner of sections 1, 6, 7, and 12, on the Guide Meridian between Ranges 6 and 7 West, hereinbefore described.

S. 89° 26.7′ W., between sections 1 and 12.

19.783 Point for the E 1/16 section corner of sections 1 and 12.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located 6 1/2 feet north of a fence line extending east and west, in piñon and juniper.

Raise a mound of stone 3x2x1 feet north of the aluminum post.

39.566 The 1/4 section corner of sections 1 and 12, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, projecting 2 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

CHAINS

Found a steel fence post alongside the galvanized post.

The position of the 1/4 section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located 2 1/2 feet north of fence line extending east and west, and 17 feet north of the centerline line of a dirt road, 20 feet wide, bearing east and west.

N. 89° 22.9' W., beginning new measurement.

39.917 The southwest corner of section 1 only, monumented with a Beaver County Survey monument, a galvanized post, 2 inches diameter, firmly set, projecting 2 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

Found a steel fence post alongside the galvanized post.

The position of the section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located in sagebrush flat.

Raise a small mound of stone east of the post.

Reestablishment of the Survey Executed by F. Dickert in 1870.

N. 0° 04.7' E., on the west boundary of section 1.

O.347 The closing corner of sections 2 and 12 only, monumented with a rebar, 5/8 inch diameter, firmly set, projecting 2 inches

CHAINS

above ground, with no cap attached and a steel fence post set alongside. This closing corner is accepted as the best available evidence of the position of the original corner.

Lying loose alongside the rebar, found a sandstone 12x10x5 inches plainly marked CC on one face, 5 notches on one edge and 1 notch on another.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar inside post, with the aluminum cap marked:

T26SR7W S <u>2 C</u> S 1 S12 C 2005

Bury the marked stone alongside the aluminum post.

Corner is located in sagebrush flat, under a power line.

From this point, the north corner of sections 11 and 12 only, bears N. 89° 55.1' W., 4.230 chains distance, hereinbefore described.

The 1/4 section corner of sections 1 and 2, monumented with a rebar, 5/8 inch diameter, firmly set, projecting 4 inches above ground, with no cap attached, set in a small mound of stone, with a steel fence post alongside. The rebar is accepted as a careful and faithful determination of the position of the 1/4 section corner by proportionate measurement. No determination was made as to who or when the rebar was set.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base and with the rebar inside the post, with the aluminum cap marked:

T26SR7W 1/4 S 2 | S 1 2005

Raise a small mound of stone to the west of the aluminum post.

Corner is located in sagebrush flat.

N. 0° 04.7' E., beginning new measurement.

CHAINS

40.264

The standard corner of sections 1, 2, 35 and 36, on the Fifth Standard Parallel South, hereinbefore described.

Reestablishment of the Survey Executed by J. Bausman in 1870 and the Resurvey Executed by Page and Erwin in 1901.

From the corner of sections 34 and 35 only, on the south boundary of the township, hereinbefore described.

N. 0° 28.5' W., on the west boundary of section 35.

20.083 Point for the S 1/16 section corner of section 35 only.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Raise a small mound of stone east of the aluminum post.

Corner is located 54 feet east of a fence line extending north and south, on gradual east slope in piñon and juniper.

39.989 Point for the 1/4 section corner of section 34 only.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a 6 feet tall cedar post alongside the aluminum post.

Raise a mound of stone 3x2x1 feet west of the aluminum post.

Corner is located on a grassy flat.

40.166 The 1/4 section corner of section 35 only, monumented with a sandstone 24x9x8 inches, firmly set, plainly marked 1/4 on the west face.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

CHAINS

T26SR7W 1/4 | s35 2005

from which

A burned juniper, with a healed over blaze bears, N. 51° E., 150 links distance.

No remaining evidence of the northwest bearing tree was found.

Corner is located on a grassy flat.

 $N.~0^{\circ}~13.8'~E.$, beginning new measurement.

39.810 Point for the closing corner of sections 27 and 34 only, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, $2\ 1/2$ inches diameter, flush with the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located on south edge of a cultivated field, on north track of a two-track road bearing east and west.

40.511 Point for the corner of sections 26 and 35 only, at proportionate distance determined by using the Irregular Boundary Adjustment Method. There is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 18 inches below the surface of the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Corner is located in a cultivated field.

Reestablishment of the Survey Executed by J. Bausman in 1870

From the corner of sections 25, 26, 35, and 36.

CHAINS

 $N.~88\,^{\circ}~52.8'~W.,$ between sections 26 and 35.

20.094 Point for the E 1/16 section corner of sections 26 and 35.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Raise a mound of stone 3x3x2 feet north of the aluminum post.

Corner is located on the west edge of an abandoned gravel pit.

40.188 The 1/4 section corner of sections 26 and 35, determined from the only remaining original bearing tree at record bearing and distance.

A juniper stump 6 inches diameter, 4 ft. high, scribed 1/4 BT on an open blaze, bears N. 69°15′ E., 193 links distance.

Lying loose in the vicinity, found a granite stone 18x9x6 inches, plainly marked 1/4 on one side. Local land owner, Robert Yardley, stated that he had seen the corner in place, but it was disturbed when a fence was erected.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 3 foot base, to the aluminum cap marked:

Bury the marked stone alongside the aluminum post.

Corner is located in a fence line extending east and west.

N. 89° 46.9' W., beginning new measurement.

40.319 The corner of sections 26 and 35 only.

CHAINS

Reestablishment of the Survey executed by J. Bausman in 1870 and the Resurvey executed by Page and Erwin in 1901.

N. 0° 00.8′ E., on the west boundary of section 26.

39.545 Point for the 1/4 section corner of section 27 only.

The corner falls in cultivated lands, not suitable for permanent monumentation and therefore not monumented.

40.512 Point for the 1/4 section corner of section 26 only, at proportionate distance, determined by using the Irregular Boundary Adjustment Method. There is no remaining evidence of the original corner.

The corner falls in cultivated lands, not suitable for permanent monumentation and therefore not monumented.

N. 0° 01.2' E., beginning new measurement.

- 19.157 Point for the N 1/16 section corner of section 27 only, not monumented.
- 20.251 Point for the N 1/16 section corner of section 26 only, not monumented.
- Point for the closing corner of sections 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Raise a mound of stone 3x1x1 feet west of the aluminum post.

Corner is located in a fence line extending north and south, between two cultivated fields.

40.502 The corner of sections 23 and 26 only, monumented with a steel fence post. This post has been utilized by others as the section corner point, and is accepted during the execution of this survey as the best available evidence of the position of the original corner. No remaining evidence of the original marked stone was found.

At the corner point

CHAINS

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W | S23 | S26 2005

Corner is located in a fence line extending north and south between two cultivated fields.

Reestablishment of the Survey Executed by J. Bausman in 1870

From the corner of sections 23, 24, 25, and 26.

N. 89° 22.2' W., between sections 23 and 26.

40.393 Point for the 1/4 section corner of sections 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 16 inches below the surface of the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W S 23 1/4 S 26 2005

Corner is located in a cultivated field.

80.786 The corner of sections 23 and 26 only.

Reestablishment of the Survey executed by J. Bausman in 1870 and the Resurvey executed by Page and Erwin in 1901.

N. 0° 05.5' W., on the west boundary of section 23.

38.713 Point for the 1/4 section corner of section 22 only.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W 1/4 | S22 | 2005

CHAINS

Corner is located 1 foot east of a fence line extending north and south on west edge of cultivated field and 20 feet east of a two-track road bearing north and south.

The 1/4 section corner of section 23 only, monumented with a lava stone 14x8x5 inches, firmly set, plainly marked 1/4 on the east face.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W 1/4 S23 2005

Bury the marked stone alongside the aluminum post.

Corner is located in a fence line extending north and south on the west edge of a cultivated field.

N. 0° 28.6' E., beginning new measurement.

The closing corner of sections 15 and 22 only, monumented with a Beaver County Survey Monument, a galvanized post, 2 inches diameter, firmly set, projecting 6 inches above ground, with an attached 3 1/4 inch diameter aluminum cap marked:

LS 174457 T26SR7W S15 S23 S22 2005

Found a steel fence post alongside the galvanized post.

The position of the section corner monument was based on the original marked stone found by the Beaver County Surveyors Office. This monument is accepted as the best available evidence of the position of the original corner.

A corner Perpetuation and Filing Record, dated October 29, 2003, is on file at the Beaver County Recorders Office.

Corner is located 1 foot north of a fence line extending N. 80° E., and S. 80° W.

37.961 The corner of sections 14 and 23 only, monumented with a 2 inch diameter brass tablet, set in a 6 inch diameter concrete cylinder, with the brass tablet marked T26S R7W S14 S23 LS145764.

Found a steel fence post alongside the concrete cylinder.

CHAINS

The plat of survey executed by Bush and Gudgell in 1987 references this corner as a found old stone. The plat of survey executed by Watson Engineering in 2001, references this corner by setting a brass cap in concrete at record distance based upon the Bush and Gudgell survey plat. No remaining evidence of the original marked stone was found, and the monument as set by Watson Engineering in 2001, is accepted as the best available evidence of the position of the original corner.

Corner is located in an area of extensive ground disturbance in pi \tilde{n} on and juniper.

From the corner of sections 13, 14, 23, and 24.

N. 89° 01.1' W., between sections 14 and 23.

- 20.254 Point for the E 1/16 section corner of sections 14 and 23, not monumented.
- 40.508 Point for the 1/4 section corner of sections 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches below the surface of the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Corner is located in a cultivated field.

60.731 Point for the W 1/16 section corner of sections 14 and 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located 10 feet east of the west edge of a cultivated field.

80.954 The corner of sections 14 and 23 only.

CHAINS

Reestablishment of the Survey Executed by Page and Erwin in 1901.

- $N.~0^{\circ}~37.5'~W.$, between sections 14 and 15.
- 19.427 Point for the S 1/16 section corner of sections 14 and 15, not monumented.
- 39.392 The 1/4 section corner of sections 14 and 15, monumented with rebar, 5/8 inch diameter, firmly set, without attached identifying cap.

Lying loose alongside the rebar, found a lava stone 18x8x6 inches, plainly marked 1/4 S 15 on one side, with a scattered mound of stone to the north.

from which

- A juniper 16 inches diameter, with no scribe marks visible on an open blaze bears, S. 62° E., 25 links distance. (Record S. 56° E., 8 links distance.)
- A juniper limb 6 inches diameter, with no scribe marks visible on an open blaze bears, N. 32° W., 15 links distance. (Record N. 65° W., 12 links distance.)

The rebar is accepted as the best available evidence of the position of the marked stone.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 10 inches in the ground to solid rock, with magnet enclosed in a clear plastic case at the base and with rebar and cap inside the post, in a mound of stone, 5 foot base to the aluminum cap marked:

T26SR7W 1/4 S15 | S14 2005

Bury the marked stone alongside the aluminum post.

Corner is located in piñon and juniper.

N. 0° 21.0' E., beginning new measurement.

40.073 The corner of sections 10, 11, 14, and 15, monumented with a lava stone 20x10x8 inches, firmly set, plainly marked 2 notches on east and 4 notches on south edges.

At the corner point

CHAINS

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W S10 | S11 S15 | S14 2005

from which

- A juniper 12 inches diameter, with a healed over blaze bears, S. 33° E., 28 links distance.
- A juniper 10 inches diameter, with no scribe marks visible on an open blaze bears, S. 57° W., 57 links distance.

Bury the marked stone alongside the aluminum post.

Corner is located on gradual east slope in piñon and juniper.

S. 89° 50.3′ E., between sections 11 and 14.

39.941 The 1/4 section corner of section 11 only, monumented with a rebar, 5/8 inch diameter, with attached 1 inch diameter yellow plastic cap marked GRIMSHAW LS174457.

Lying loose alongside the rebar, found a lava stone 16x8x8 inches, dimly marked 1/4 on face.

From which

- A juniper 16 inches diameter, scribed 1/4 visible, bears, S. 26° E., 15 links distance.
- A juniper 30 inches diameter, with faint visible scribing on a mostly healed blaze bears, N. 35° W., 4 links distance. (Record North, 5 links distance)

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar and cap inside the post, with the aluminum cap marked:

T26SR7W 1/4 S 11 2005

Bury the marked stone alongside the aluminum post.

Set a steel fence post along side the aluminum post.

CHAINS

Corner is located in piñon and juniper flat.

From this corner, the corner of fences, extending east and south bears, N. 35° W., 2 feet distance.

S. 89° 48.0' E., beginning new measurement.

O.811 The point for the 1/4 section corner of section 14 only, monumented with a rebar, 5/8 inch diameter, with attached 2 1/2 inch diameter aluminum cap marked GRIMSHAW SURVEYING 1/4 S14 LS174457 2003. The rebar with cap are accepted as a careful and faithful determination of the 1/4 section corner position.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar and cap inside the post, with the aluminum cap marked:

T26SR7W

1/4 S 14
2005

Set a steel fence post along side the aluminum post.

Corner is located in piñon and juniper flat 3.5 feet south of a fence line extending east and west.

40.091 The corner of sections 11 and 12 only, hereinbefore described.

S. 89° 48.0' E., between sections 12 and 14.

0.825 The closing corner of sections 12 and 14, hereinbefore described.

From the corner of sections 27, 28, 33, and 34, monumented with a trachyte stone $18 \times 10 \times 8$ inches, firmly set, plainly marked 1 notch on south and 5 notches on north edges.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 3 foot base to the aluminum cap marked:

T26SR7W <u>S28 | S27</u> <u>S33 | S34</u> 2005

CHAINS

Bury the marked stone alongside the aluminum post.

Set a steel fence post along side the aluminum post.

Corner is located on steep northeast slope in underbrush.

From this corner, National Geodetic Survey Station "PINEY" monumented with a standard disk stamped PINEY 1938, cemented in a rock, in a mound of stone, bears, S. 57°00.2′ W. (FWD), N. 56°59.6′ E. (REV), 90.690 chains distance.

 $N.\ 0^{\circ}\ 02.7'$ E., between sections 27 and 28 on the sectional guide meridian.

40.082 The 1/4 section corner of sections 27 and 28, monumented with a trachyte stone, 12x10x8 inches, firmly set, dimly marked 1/4 S on the west face and 27 on the east face and a mound of stone 3x2x1 feet west.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W 1/4 S28 | S27 2005

Bury the marked stone alongside the aluminum post.

Set a steel fence post along side the aluminum post.

Corner is located on gradual east slope in open grass.

N. 0° 02.5' E., beginning new measurement

40.150 The corner of sections 21, 22, 27, and 28, monumented with an aluminum post, 2 1/2 inches diameter, firmly set, projecting 4 inches above ground, with the aluminum cap marked as described in the official record of the resurvey executed by L.V. Judd in 1996.

From the corner of sections 27, 28, 33, and 34.

N. 89° 56.0' E., between sections 27 and 34.

40.093 The 1/4 section corner of sections 27 and 34 monumented with a sandstone 16x12x5 inches, firmly set in a small mound of stone, plainly marked 1/4 27 on the north and 34 on the south faces.

Found a steel fence post alongside the marked stone.

CHAINS

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Bury the marked stone alongside the aluminum post.

Raise a mound of stone 3x2x1 feet north of the aluminum post.

Corner is located in a flat open area.

N. 89° 56.8' E., beginning new measurement.

20.029 Point for the E 1/16 section corner of sections 27 and 34.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Raise a mound of stone 3x3x3 feet north of the aluminum post.

Corner is located 70 feet south of a fence corner extending north and east.

39.907 The closing corner of sections 27 and 34.

From the corner of sections 21, 22, 27, and 28.

N. 89° 45.2' E., between sections 22 and 27.

40.012 Point for the 1/4 section corner of sections 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

CHAINS

Set a steel fence post alongside the aluminum post.

Corner is located in a cultivated field, 22.5 feet east of a fence line extending north and south.

- 60.018 Point for the E 1/16 section corner of sections 22 and 27, not monumented.
- 79.924 The closing corner of sections 22 and 27.

The Subdivision of Section 1, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of sections 1 and 12.

N. 0° 11.3' E., on the N - S centerline of section 1.

- 20.242 Point for the center S 1/16 section corner of section 1, not monumented.
- 40.484 The center 1/4 section corner of section 1, monumented with a rebar 5/8 inch diameter, firmly set, with no identifying cap attached, and a steel fence post alongside.

The rebar is accepted as a careful and faithful determination of the center 1/4 section corner position. No determination was made as to who or when this monument was set.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 22 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar inside the post, in a mound of stone, 3 ft. base to the aluminum cap marked:

T26SR7W C 1/4 S 1 2005

Corner is located in sagebrush flat.

80.824 The standard 1/4 section corner of sections 1 and 36, on the Fifth Standard Parallel South, hereinbefore described.

From the 1/4 section corner of sections 1 and 6, on the Guide Meridian between Ranges 6 and 7 West, hereinbefore described.

THE SUBDIVISION OF SECTION 1, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

N. 89° 58.9' W., on the E - W centerline of section 1.

- 19.841 Point for the center E 1/16 section corner of section 1, not monumented.
- 39.682 The center 1/4 section corner of section 1.
- 59.676 Point for the center W 1/16 section corner of section 1.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located in sagebrush flat.

79.670 The 1/4 section corner of sections 1 and 2.

From the E 1/16 section corner of sections 1 and 12.

N. 0° 16.6' E., on the N - S centerline of SE 1/4 of section 1.

20.143 The SE 1/16 section corner, monumented with a rebar, 5/8 inch diameter, firmly set, with no identifying cap attached, and a steel fence post alongside.

The rebar is accepted as a careful and faithful determination of the 1/16 section corner position. No determination was made as to who or when this monument was set.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 20 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar inside post, in a mound of stone, 2 foot base to the aluminum cap marked:

Corner is located in piñon and juniper.

40.286 Point for the center E 1/16 section corner of section 1.

From the S 1/16 section corner of sections 1 and 6, on the Guide Meridian between Ranges 6 and 7 West, hereinbefore described.

THE SUBDIVISION OF SECTION 1, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

S. 89° 43.9' W., on the E - W centerline of the SE 1/4 of section 1.

- 19.812 The SE 1/16 section corner of section 1.
- 39.624 Point for the center S 1/16 section corner of section 1.

From the center W 1/16 section corner of section 1.

N. 0° 08.0' E., on the N - S centerline of the NW 1/4 of section 1.

40.302 The W 1/16 section corner of sections 1 and 36 on the Fifth Standard Parallel South, hereinbefore described.

The Subdivision of Section 12, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of sections 12 and 13.

N. 1° 21.9' E., on the N - S centerline of section 12.

39.219 Point for the center 1/4 section corner, at intersection with the E-W center line of section 12.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W C 1/4 S 12 2005

Set a steel fence post alongside the aluminum post.

Raise a small mound of stone west of the aluminum post.

Corner is located in piñon and juniper.

58.985 Point for the center N 1/16 section corner of section 12.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

C N 1/16 S12 C 2005

Set a steel fence post alongside the aluminum post.

THE SUBDIVISION OF SECTION 12, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

From this corner, a rebar, with attached 2 inch diameter aluminum cap marked GRIMSHAW SURVEYING CEN N $1/16~\rm S12$ LS174457, bears S. 1° 21.9 W. 4.3 ft. distance, this was not utilized.

Corner is located in piñon and juniper.

78.751 The 1/4 section corner of sections 1 and 12.

From the 1/4 section corner of sections 7 and 12, on the Guide Meridian, between Ranges 6 and 7 West, hereinbefore described.

N. 89° 38.7' W., on the E - W centerline of section 12.

- 39.940 The center 1/4 section corner of section 12.
- 60.250 The center W 1/16 section corner of section 12, monumented with a rebar, 5/8 inch diameter, with attached 2 inch diameter aluminum cap marked GRIMSHAW SURVEYING CEN W 1/16 LS174457.

The rebar is accepted as a careful and faithful determination of the center W 1/16 section corner position.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar and cap inside post, with the aluminum cap marked:

Corner is located on flat ground in scattered juniper.

N. 89° 38.7' W., beginning new measurement.

22.885 The 1/4 section corner of sections 11 and 12.

From the W 1/16 section corner of sections 12 and 13.

N. 2° 01.0' E., on the N - S centerline of SW 1/4 of section 12.

38.445 The center W 1/16 section corner of section 12.

From the center N 1/16 section corner of section 12.

N. 89° 18.6' W., on the E - W centerline of the NW 1/4 of section 12.

THE SUBDIVISION OF SECTION 12, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

43.672 The N 1/16 section corner of sections 11 and 12.

The Subdivision of Section 13, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of sections 13 and 24.

N. 0° 13.1' W., on the N - S centerline of section 13.

41.325 Point for the center 1/4 section corner, at intersection with the E - W centerline of section 13.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W C 1/4 S 13 2005

Raise a mound of stone 3x2x1 feet west of the aluminum post.

Corner is located on flat ground, in an old chaining in piñon and juniper.

81.378 The 1/4 section corner of sections 12 and 13.

From the 1/4 section corner of section 13 only, on the Guide Meridian, between Ranges 6 and 7 West, hereinbefore described.

N. 88° 06.7' W., on the E - \overline{W} centerline of section 13.

- 40.104 The center 1/4 section corner of section 13.
- 60.861 Point for the center W 1/16 section corner of section 13.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Raise a mound of stone 3x2x1 feet, north of the aluminum post.

Set a cedar post, 4 feet long alongside the aluminum post.

Corner is located on flat ground.

From this corner, the corner of fences extending south and west, bears N. 47° E., 43 feet distance.

THE SUBDIVISION OF SECTION 13, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

81.618 The 1/4 section corner of sections 13 and 14.

From the W 1/16 section corner of sections 13 and 24.

 $N.~0^{\circ}~11.9^{\circ}~W.$, on the N - S centerline of SW 1/4 of section 13.

41.924 The center W 1/16 section corner of section 13.

From the center W 1/16 section corner of section 13.

 $N.~0^{\circ}~12.0^{\circ}~W.$, on the N - S centerline of the NW 1/4 of section 13.

40.281 The W 1/16 section corner of sections 12 and 13.

The Subdivision of Section 14, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of sections 14 and 23.

N. 0° 05.7' E., on the N - S centerline of section 14.

20.345 Point for the center S 1/16 section corner of section 14.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located in a cultivated field.

40.961 Point for the center 1/4 section corner of section 14, at intersection with the E - W centerline.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W C 1/4 S14 2005

Set a steel fence post alongside the aluminum post.

THE SUBDIVISION OF SECTION 14, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

From this corner, a fence corner, with fences extending north, east, and S. 40° W., bears S. 10° E., 49 feet.

80.036 The 1/4 section corner of section 14 only.

From the 1/4 section corner of sections 13 and 14.

S. 88° 46.0' W., on the E - W centerline of section 14.

- 40.304 The center 1/4 section corner of section 14.
- 60.573 Point for the center W 1/16 section corner of section 14, not monumented.
- 81.249 The 1/4 section corner of sections 14 and 15.

From the W 1/16 section corner of sections 14 and 23.

 $N.~0^{\circ}~01.9'~E.$, on the N - S centerline of SW 1/4 of section 14.

19.886 Point for the SW 1/16 section corner of section 14, at intersection with the E - W centerline of the SW 1/4.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

SW 1/16 S14 2005

Set a steel fence post alongside the aluminum post.

Corner is located 25 feet east of a fence line, with fences extending north and south in piñon and juniper.

40.180 The point for the center W 1/16 section corner of section 14.

From the center S 1/16 section corner of section 14.

S. 89° 40.7' W., on the E - W centerline of the SW 1/4 of section 14.

- 20.243 The SW 1/16 section corner of section 14.
- 40.686 The point for the S 1/16 section corner of sections 14 and 15.

The Subdivision of Section 23, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

THE SUBDIVISION OF SECTION 23, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

N. 0° 13.4' E., on the N - S centerline of section 23.

- 40.964 Point for the center 1/4 section corner of section 23, at intersection with the E W centerline. The corner point falls within the Interstate 15 corridor, where it is impractical to monument, not monumented.
- 60.068 Point for the center N 1/16 section corner of section 23, not monumented.
- 79.172 The 1/4 section corner of sections 14 and 23.

From the 1/4 section corner of sections 23 and 24.

N. 88° 40.3' W., on the E - W centerline of section 23.

20.196 Point for the center E 1/16 section corner of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 3 foot base to the aluminum cap marked:

Corner is located in flat open brush 30 feet east of the centerline of a gravel road, 30 feet wide, bearing north and south.

- 40.392 The point for the center 1/4 section corner of section 23.
- 81.014 The 1/4 section corner of section 23 only.

From the center E 1/16 section corner of section 23.

 $N.~0^{\circ}~18.9^{\circ}~E.$, on the N-S centerline of the NE~1/4 of section 23.

19.165 Point for the NE 1/16 section corner, at intersection with the E - W center line of the NE 1/4 of section 23.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, flush with the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

THE SUBDIVISION OF SECTION 23, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Corner is located at north end of turn around for dumpster on old highway 91.

From this corner, a rebar with attached cap marked REW 145764 bears S. 6° 34' W., 54.0 ft. distance, not utilized.

38.330 The point for the E 1/16 section corner of sections 14 and 23.

From the N 1/16 section corner of sections 23 and 24.

N. 88° 50.7' W., on the E - W centerline of the NE 1/4 of section 23.

- 20.224 The NE 1/16 section corner of section 23.
- 40.448 The point for the center N 1/16 section corner of section 23.

The Subdivision of Section 24, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of sections 24 and 25.

N. 1° 26.7' E., on the N - S centerline of section 24.

39.925 Point for the center 1/4 section corner of section 24, at intersection with the E - W center line.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 6 foot base, 4 feet high to the aluminum cap marked:

T26SR7W C 1/4 S 24 2005

Corner is located on steep north slope 27 feet south of a two-track road bearing N. 70° W. and S. 70° E., and 53 feet south of Pine Creek, 12 feet wide, 3 feet deep, bearing S. 64° E., and N. 64° W.

- 59.518 Point for the center N 1/16 section corner of section 24, not monumented.
- **79.111** The 1/4 section corner of sections 13 and 24.

From the 1/4 section corner of section 24 only, on the Guide Meridian, between Ranges 6 and 7 West, hereinbefore described.

N. 88° 45.1' W., on the E - W centerline of section 24.

40.768 The center 1/4 section corner of section 24.

THE SUBDIVISION OF SECTION 24, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

- 61.176 Point for the center W 1/16 section corner of section 24, not monumented.
- 81.584 The 1/4 section corner of sections 23 and 24.

From the point for the center W 1/16 section corner of section 24.

N. 0° 55.9' E., on the N - S centerline of the NW 1/4 of section 24.

19.408 Point for the NW 1/16 section corner of section 24, at intersection with the E - W center line of the NW 1/4.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 20 inches in the ground to solid rock, with magnet enclosed in a clear plastic case at the base, in a mound of stone, 3 foot base to the aluminum cap marked:

NW 1/16 S 24 2005

Set a steel fence post alongside the aluminum post.

Corner is located on gentle north slope in open brush.

From this corner, the corner of fences extending north and west, bears N. 30° E., 39 feet distance.

38.816 The W 1/16 section corner of sections 13 and 24.

From the point for the center N 1/16 section corner of section 24

N. 89° 15.9' W., on the E - W centerline of the NW 1/4 of section 24.

- 20.583 The NW 1/16 section corner of section 24.
- 41.166 The N 1/16 section corner of sections 23 and 24.

The Subdivision of Section 27, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of sections 27 and 34.

N. 0° 00.6' W., on the N - S centerline of section 27.

40.160 Point for the center 1/4 section corner of section 27, at intersection with the E - W center line.

THE SUBDIVISION OF SECTION 27, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W C 1/4 S 27 2005

Set a steel fence post alongside the aluminum post.

Corner is located on sagebrush flat in piñon and juniper.

60.259 Point for the center N 1/16 section corner of section 27.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located 25 feet east of a dirt road 20 feet wide, bearing N. 10° W., and S. 10° E, on sagebrush flat.

From this corner, a corner of fences with fences extending north, east, and west, bears N. 14° W., 83.9 feet distance.

80.358 The 1/4 section corner of sections 22 and 27.

From the point for the 1/4 section corner of section 27 only.

S. 89° 49.3' W., on the E - W centerline of section 27.

19.898 Point for the center E 1/16 section corner of section 27.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located 4.8 feet east of a fence line extending north and south on west edge of a cultivated field.

39.921 The center 1/4 section corner of section 27.

THE SUBDIVISION OF SECTION 27, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

79.972 The 1/4 section corner of sections 27 and 28.

From the center E 1/16 section corner of section 27.

N. 0° 01.9' W., on the N - S centerline of NE 1/4 of section 27.

20.111 Point for the NE 1/16 section corner of section 27, at intersection with the E - W center line of the NE 1/4.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 26 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

NE 1/16 S 27 2005

Corner is located in a cultivated field.

From this corner, a corner of fences with fences extending N. 80° W., and south, bears N. 5° W., 52.6 feet distance.

40.222 The point for the E 1/16 section corner of sections 22 and 27.

From the point for the N 1/16 section corner of section 27 only.

S. 89° 47.2' W., on the E - W centerline of the NE 1/4 of section 27.

- 19.902 The NE 1/16 section corner of section 27.
- 39.917 The center N 1/16 section corner of section 27.

From the E 1/16 section corner of sections 27 and 34.

 $N.~0^{\circ}~00.8^{\circ}~W.$, on the N - S centerline of the SE 1/4 of section 27.

40.203 The center E 1/16 section corner of section 27.

The Subdivision of Section 35, T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

From the 1/4 section corner of section 35 only, on the south boundary of the township, hereinbefore described.

N. 0° 00.6' E., on the N - S centerline of section 35.

19.648 Point for the center S 1/16 section corner of section 35.

THE SUBDIVISION OF SECTION 35, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Corner is located on flat ground in an old chaining.

39.296 Point for the center 1/4 section corner of section 35, at intersection with the E - W center line.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 29 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

T26SR7W C 1/4 S 35 2005

Set a steel fence post alongside the aluminum post.

Corner is located on flat pasture ground.

From this corner, the corner of fences extending S. 20° E. and N. 10° E., bears, S. 10° E., 60.5 feet distance.

59.196 Point for the center N 1/16 section corner of section 35.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:

Set a steel fence post alongside the aluminum post.

Raise a small mound of stone west of the aluminum cap.

Corner is located 7 feet north of a fence line extending east and west on flat ground in pasture.

79.096 The 1/4 section corner of sections 26 and 35.

From the 1/4 section corner of sections 35 and 36.

s. 89° 12.5′ W., on the E - W centerline of section 35.

THE SUBDIVISION OF SECTION 35, T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

- 20.089 Point for the center E 1/16 section corner of section 35, not monumented.
- 40.178 The center 1/4 section corner of section 35.
- 80.660 The 1/4 section corner of section 35 only.

From the point for the center E 1/16 section corner of section 35.

 $N.~0^{\circ}~01.1'~E.$, on the N - S centerline of NE 1/4 of section 35.

19.565 Point for the NE 1/16 section corner of section 35, at intersection with the E - W centerline of the NE 1/4.

The corner point falls within an active gravel pit, not suitable for permanent monumentation at this time, and therefore not monumented.

39.130 The E 1/16 section corner of sections 26 and 35.

From the point for the N 1/16 section corner of sections 35 and 36.

N. 89° 50.1' W., on the E - W centerline of the NE 1/4 of section 35.

- 20.088 The point for the NE 1/16 section corner of section 35.
- 40.176 The center N 1/16 section corner of section 35.

From the center S 1/16 section corner of section 35.

S. 88° 35.3' W., on the E - W centerline of the SW 1/4 of section 35.

40.323 The S 1/16 section corner of section 35 only.

DEPENDENT RESURVEY OF WASHINGTON LOAD, LOT 57A, AM., (GORDON MINING DISTRICT), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Dependent Resurvey of Washington Lode, Lot 57A, AM., (Gordon Mining District), T. 26 S., R. 7 W., Salt Lake Meridian, Utah.

Reestablishment of the Survey executed by E. Koeber in 1886 and the Amended Survey executed by O. Palmer in 1891

From Corner Number 1, Washington Lode, Lot 57A, AM., monumented with an iron pipe, 2 1/2 inches diameter, firmly set in a mound of stone, 3 ft. base, with an attached metal tag marked:

USI C 1 57 A

This corner is accepted as a careful and faithful reestablishment of the original corner, not remonumented.

No remaining evidence of the original cedar corner post was found.

No remaining evidence of the bearing tree was found.

Corner is located on northwest slope in piñon and juniper.

From this corner, the corner of sections 7, 12, 13, and 18, bears S. 32° 50.8' E., 17.013 chains distance.

N. 28° 24.0' W., on line 1-2.

9.048 Corner Number 2, monumented with an iron pipe, 2 1/2 inches diameter, firmly set in a mound of stone, 3 foot base, with attached metal tag marked:

USI C 2 57 A

This corner is accepted as a careful and faithful reestablishment of the original corner, not remonumented.

No remaining evidence of the original cedar corner post was found.

No remaining evidence of the bearing tree was found.

Corner is located 16.5 feet west of a barbed wire fence extending north and south, in piñon and juniper.

N. 61° 36.8′ E., on line 2-3.

DEPENDENT RESURVEY OF WASHINGTON LOAD, LOT 57A, AM., (GORDON MINING DISTRICT), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

3.107 Intersect line 2-3, Newark Lode, Lot 58, AM.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:



Set a steel fence post alongside the aluminum post.

Raise a mound of stone, 3x2x1 feet north of the aluminum post.

Corner is located in flat open brush, 30 feet east of the centerline of a gravel road, 30 feet wide, bearing north and south.

- 8.589 Intersect line 1-2, Newark Lode, Lot 58, AM., not monumented.
- 13.461 Corner Number 3, monumented with a rebar, next to a wood stake, driven in the center of a rusted off 2 1/2 inch diameter iron pipe, with attached tag marked, USI C 3 57 A, with a mound of stone to the south, and a steel fence post alongside.

This corner is accepted as a careful and faithful reestablishment of the original corner.

No remaining evidence of the original cedar corner post was found.

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 24 inches in the ground, with magnet enclosed in a clear plastic case at the base, over the rebar and iron pipe, with the aluminum cap marked:



Set a steel fence post alongside the aluminum post.

Raise a mound of stone south of the aluminum post.

Corner is located on an open south slope.

DEPENDENT RESURVEY OF WASHINGTON LOAD, LOT 57A, AM., (GORDON MINING DISTRICT), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

- s. 28° 24.0' E., on line 3-4.
- 4.521 Intersect the Guide Meridian between Ranges 6 and 7 West, not monumented.
- 9.048 Point for Corner Number 4, determined by the intersection of lines parallel with the north and west boundaries of the lode. No remaining evidence of the original corner was found.

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base, with the aluminum cap marked:



Set a steel fence post alongside the aluminum post.

Corner is located on sulphur flat in area of extensive ground disturbance.

- s. 61° 36.8′ W., on line 4-1.
- 2.557 Intersect the Guide Meridian between Ranges 6 and 7 West, not monumented.
- 13.461 Corner Number 1, Washington Lode, Lot 57A, AM.

Dependent Resurvey of Newark Lode, Lot 58, AM., (Gordon Mining District), Salt Lake Meridian, Utah.

Reestablishment of the Survey executed by E. Koeber in 1886 and the Amended Survey executed by O. Palmer in 1891

From Corner Number 1, Newark Lode, Lot 58, AM., monumented with a rebar, 5/8 inch diameter, firmly set, with a steel fence post alongside.

This corner is accepted as a careful and faithful reestablishment of the original corner.

No remaining evidence of the original cedar corner post was found.

At the corner point

DEPENDENT RESURVEY OF NEWARK LODE, LOT 58, AM., (GORDON MINING DISTRICT), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base and with the rebar inside the post, with the aluminum cap marked:



Corner is located at top of south sloping hill on bench cut for a road.

From this corner, the 1/4 section corner of sections 7, 12, bears N. 18° 54.7' E., 11.100 chains distance.

s. 42° 53.8′ W., on line 1-2.

- 4.602 Intersect line 2-3, Washington Lode, Lot 57A, AM.
- 9.088 Corner Number 2, monumented with an iron pipe, 2 1/2 inches diameter, firmly set, projecting 18 inches above ground, with attached metal tag marked:

USI C 2 58

This corner is accepted as a careful and faithful reestablishment of the original corner, not remonumented.

No remaining evidence of the original cedar corner post was found.

Set a steel fence post alongside the aluminum post.

Corner is located on a northeast slope in oak brush.

N. 68° 57.3' W., on line 2-3.

- 1.895 Intersect line 2-3, Washington Lode, Lot 57A, AM.
- 21.098 Corner Number 3, monumented with an iron pipe, 2 1/2 inches diameter, firmly set in a mound of stone, with an attached metal tag marked:

DEPENDENT RESURVEY OF NEWARK LODE, LOT 58, AM., (GORDON MINING DISTRICT), T. 26 S., R. 7 W., SALT LAKE MERIDIAN, UTAH.

CHAINS

This corner is accepted as a careful and faithful reestablishment of the original corner, not remonumented.

No remaining evidence of the original cedar corner post was found.

Set a steel fence post alongside the aluminum post.

N. 43° 02.8' E., on line 3-4.

9.088 Corner Number 4, monumented with a rebar, in a small mound of stone, with attached cap marked:

LS 4493 451 SEI 12-88

This corner is accepted as a careful and faithful reestablishment of the original corner.

No remaining evidence of the original cedar corner post was found

At the corner point

Set an aluminum post, 30 inches long, 2 1/2 inches diameter, 28 inches in the ground, with magnet enclosed in a clear plastic case at the base and with rebar and cap inside post, with the aluminum cap marked:



2005

Set a steel fence post alongside the aluminum post.

s. 68° 58.7' E., on line 4-1.

21.075 Corner Number 1, Newark Lode, Lot 58, AM.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

Name	Capacity
Larry V. Judd	Cadastral Surveyor
Scott Bishop	Cadastral Surveyor
Jeremy Davis	Survey Technician
Samantha Hamblin	Survey Aid

CERTIFICATE OF SURVEY

I, Ronald K. Baugh, Supervisory Cadastral Surveyor, hereby certify upon honor, that in pursuance of Special Instructions bearing the date 24th day of March, 2005, have executed a dependent resurvey of a portion of the Fifth Standard Parallel South (north boundary), a portion of the Guide Meridian between Ranges 6 and 7 West (east boundary), a portion of south boundary, a portion of the subdivisional lines, the subdivision of sections 1, 12, 13, 14, 23, 24, 27 and 35, and the dependent resurvey of Washington Lode, Lot 57A, AM. and Newark Lode, Lot 58, AM., in Township 26 South, Range 7 West, of the Salt Lake Meridian, in the State of Utah, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said Special Instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

July 23 2009

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT Salt Lake City, Utah

The foregoing field notes of the dependent resurvey of a portion of the Fifth Standard Parallel South (north boundary), a portion of the Guide Meridian between Ranges 6 and 7 West (east boundary), a portion of the south boundary, a portion of the subdivisional lines, the subdivision of sections 1, 12, 13, 14, 23, 24, 27 and 35, and the dependent resurvey of Washington Lode, Lot57A, AM. and Newark Lode, Lot 58, AM., in Township 26 South, Range 7 West, Salt Lake Meridian, Utah, executed by Ronald K. Baugh, Supervisory Cadastral Surveyor having been critically examined and found correct, are hereby approved.

July 24,2009

(Chief Cadastral Surveyor for Utah)

urveyor)

```
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0000.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0000.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0001.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0001.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0002.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0002.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0003.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0003.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0004.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0004.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0005.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0005.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0006.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0006.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0007.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0007.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0008.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0008.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0009.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0009.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0010.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0010.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0011.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0011.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0012.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0012.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0013.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0013.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0014.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0014.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0015.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0015.tif
2009.12.01 10:42 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0016.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0016.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0017.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0017.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0018.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0018.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0019.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0019.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0020.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0020.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0021.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0021.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0022.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0022.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0023.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0023.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0024.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0024.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0025.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0025.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0026.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0026.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0027.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0027.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0028.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0028.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0029.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0029.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0030.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0030.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0031.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0031.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0032.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0032.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0033.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0033.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0034.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0034.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0035.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0035.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0036.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0036.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0037.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0037.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0038.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0038.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0039.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0039.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0040.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0040.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0041.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0041.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0042.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0042.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0043.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0043.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0044.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0044.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0045.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0045.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0046.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0046.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0047.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0047.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0048.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0048.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0049.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0049.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0050.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0050.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0051.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0051.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0052.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0052.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0053.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0053.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0054.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0054.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0055.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0055.tif
2009.12.01 10:43 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0056.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0056.tif
2009.12.01 10:44 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0057.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0057.tif
2009.12.01 10:44 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0058.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0058.tif
2009.12.01 10:44 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0059.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0059.tif
2009.12.01 10:44 B T:\field_notes\rectangular_ notes\newscans\r1001\r1001-0060.tif --> ut.wc.blm.gov /ext/doc/LandRecords/Survey_Plats/fieldnotes r1001-0060.tif
```